



**National
Aeronautical
Laboratory**

Documentation Sheet

Document Classification

Restricted

Title : Report on the Investigations on Failed Hydraulic Booster Jack

Document No.

PD MT 8914

Date of issue: April 1989

Author(s) : A.C.Raghuram, R.Rangaraju and M.A.Venkataswamy

Contents 1 page
5 figures

Division : Materials Science Division

No. of copies: 12

External participation : -

NAL Project No.

MT- 9- 001

Sponsor : -

Sponsor's Project No.

Approval : Dr A.C.Raghuram

26

Remarks : -

Keywords : Hydraulic Booster Jack

Abstract : The fractured shaft of a hydraulic booster jack of a fighter aircraft is analysed to find out the cause of failure. This investigation was carried out at the request of the Court of Inquiry.